


USDA FOREST SERVICE

CLEARING LIMITS


BRUSHING IS NOT PART OF THIS CONTRACT. DO NOT CUT BRUSH.



FS-7700-62 (2/92)
NEZ PERCE (3/95)

USDA FOREST SERVICE

**ATV ONLY
CLEARING LIMITS**



CLEARING LIMITS (FT.)

STATION	UPHILL	DOWNHILL	HEIGHT
ALL	4'	4'	10'


STUMP HEIGHT REQUIREMENTS * (INCHES)

STUMP POSITION	SIDE SLOPE	UPHILL	DOWNHILL
STUMPS LEFT IN PLACE BETWEEN THE TRAILWAY AND CLEARING LIMITS	SIDE SLOPE LESS THAN 10%	3	3
	SIDE SLOPE OVER 10%	3	6
STUMPS OUTSIDE THE CLEARING LIMITS	SIDE SLOPE LESS THAN 10%	3	6
	SIDE SLOPE OVER 10%	3	6

*ALL HEIGHTS MEASURED FROM UPHILL SIDE OF STUMPS.

USDA FOREST SERVICE

CLEARING LIMITS



CLEARING LIMITS (FT.)

STATION	UPHILL	DOWNHILL	HEIGHT
ALL	4'	4'	10'


STUMP HEIGHT REQUIREMENTS * (INCHES)

STUMP POSITION	SIDE SLOPE	UPHILL	DOWNHILL
STUMPS LEFT IN PLACE BETWEEN THE TRAILWAY AND CLEARING LIMITS	SIDE SLOPE LESS THAN 10%	3	3
	SIDE SLOPE OVER 10%	3	6
STUMPS OUTSIDE THE CLEARING LIMITS	SIDE SLOPE LESS THAN 10%	3	6
	SIDE SLOPE OVER 10%	3	6

*ALL HEIGHTS MEASURED FROM UPHILL SIDE OF STUMPS.

EXHIBIT 1

USDA FOREST SERVICE



STANDARD